1. LAST FLIGHT OF TRAINING SERIES WAS A SIMULATED MISSION PERFORMED THURSDAY, 24. DURING GCA FINAL, 7 MILES FROM THE FIELD THE ENGINE FLAMED OUT. RESTART ATTEMPTS WERE UNSUCCESSFUL. PILOT LANDED GEAR UP ON A SMALL CLIDER FIELD. PILOT UNHURT, AIRCRAFT BADLY DAMAGED.

ATTN: C.L. JOHNSON FROM

- 2. FUEL TOTALIZER 82 GALLONS AT FLAMEOUT. LOW LEVEL LIGHT CAME ON DURING GCA MANEUVERS AT TWELVE THOUSAND FT AND TOTALIZER READING 10/2 GALLONS. ASSUME THAT ALL FUEL TANKS ARE EMPTY BUT THIS HAS NOT BEEN VERIFIED. SUSPECT INTERMITTENT FAULT IN FUEL COUNTER SYSTEM PUZZLED AT SHORTNESS OF TIME BETWEEN LOW LEVEL LIGHT AND FLAMEOUT. TOTAL TIME OF FLIGHT WAS EIGHT AND ONE HALF HOURS.
- 3. THE WINGS ARE NOT BADLY DAMAGED BUT THE FUESELAGE IS.
  WHETHER IT IS REPAIRABLE ISN'T YET OBVIOUS. DISASSEMBLY WILL BE VERY
  DIFFICULT AND THIS WORK NOW PROCEEDING.
  - 4. IF PHONE CALL DESIRED LET ME KNOW.

END OF MESSAGE